|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipelines water Supply works at ward No. 03.

Address:

Location: Chikkabettahalli **Topography** Magnetic Soil

Soil Type : Gravatic Stone **Rock Type:** hard rock.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬಿ.ಡಬ್ಲ್ಯು.ಎಸ್.ಎಸ್.ಬಿ. ಬೆಂಗಳೂರು-10

RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 900-1100 **Yield :** 530-750-980.

Casing Pipe Required : 60.80 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1

Remarks: —

Rain Water Harvesting Compulsory

for Samrudhi Ground Water Co.

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

AE

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipelines water Supply works at ward no 03

Address: _____

_____

Location: Basavalingappa layout **Topography** Magenetic Soil

Soil Type : Gravatic Stone **Rock Type:** hard rock.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಜಿ.ಬಿ.ಡಿ. ಬೆಂಗಳೂರು-106

RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 900-1100 **Yield :** 530-750-950

Casing Pipe Required : 60-80 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: – **Point Location :** 1 ☐ ☐ ☐

Remarks: –

Rain Water Harvesting Compulsory

for Samrudhi Ground Water Consultant

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

AE

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Praviding borewell water pipe lines water Supply works at ward No.03.

Address:

Location: Dodda Bettahalli **Topography** Magnetic Soil

Soil Type : Gravatii Stone. **Rock Type:** hard rock.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2'

Depth Recommended : 900 - 1100 **Yield :** 538 - 7-70 - 980.

Casing Pipe Required : 60.80 MS. **Aquifers :** G.P. H. 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks: —

Rain Water Harvesting Compulsory

for Samrudhi Ground Water Consultant

Note: The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipe lines water Supply works at ward No. 03.

Address:

Location: Dodda gettahalli layout **Topography** Magnetic Soil

Soil Type : Gravatic stone. **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 1000 - 1200 **Yield :** 535 - 760 - 960

Casing Pipe Required : 60.80 MS. **Aquifers :** G.P.H. 2000.

PVC Outer Casing if Required: — **Point Location :** 1

Remarks: —

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಜ.ಜ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-೫೬

for Samrudhi Ground Water Consultant

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipe lines water Supply works at ward No. 03.

Address: _____

Location: Anantapura. lake. **Topography** Magnetic Soil

Soil Type : Gravatic stone. **Rock Type:** hard rock.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-10೬

RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 900 - 1100 **Yield :** 550 - 780 - 960.

Casing Pipe Required : 60.80 MS **Aquifers :** G.P.H. 2000.

PVC Outer Casing if Required: — **Point Location :** 1

Remarks: —

Rain Water Harvesting Compulsory

for Samrudhi Ground Water Co-

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing Borewell water pipe lines water Supply works at ward No.03.

Address: _____

Location: Adithya Nagara near over head tank. **Topography** Magnetic Soil

Soil Type : Gravatic Stone. **Rock Type:** hard rock.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಯುವ ಸಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬೆಂಗಳೂರು-106

RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 900-1100 **Yield :** 540-770-980.

Casing Pipe Required : 60.80 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1

Remarks: —

Rain Water Harvesting Compulsory

for Samrudhi Ground Water Consultant

Note: The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

Mr. Bharath Raj

Scanned by CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Bharath : 98459 93652
Kavitha : 9964702826

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipe lines water Supply. works at ward 100-03.

Address:

Location: Adithya Nagara (Near Temple) **Topography** Magnetic Soil

Soil Type : Gravatic Stone. **Rock Type:** hard rock.





RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2"

Depth Recommended : 900 - 1100 **Yield :** 530 - 760 - 990.

Casing Pipe Required : 60 · 80 MS **Aquifers :** G.P.H - 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks: —

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

for Samrudhi Ground Water Consultant

Mr. Bharath Raj

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿ
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಬಿ.ಡಬ್ಲ್ಯು.ಎಸ್.ಎಸ್.ಬಿ. ಬೆಂಗಳೂರು-೫೬

Scanned by CamScanner